NEVER CUT THESE MATERIALS

WARNING: Because many plastics are dangerous to cut, it is important to know what kind you are planning to use. Make has a How-To for identifying unknown plastics with <u>a simple process</u>.

Material	DANGER!	Cause/Consequence		
PVC (Poly Vinyl Chloride)/vinyl/pleather/artificial leather	Emits pure chlorine gas when cut!	Don't ever cut this material as it will ruin the optics, cause the metal of the machine to corrode, and ruin the motion control system.		
Thick (>1mm) Polycarbonate/Lexan	Cut very poorly, discolor, catch fire	pecause polycarponate strongly ansorps intrared radiation. This is the tredilency of light the laser cutter uses to cut		
ABS	Emits cyanide gas and tends to melt			
HDPE/milk bottle plastic	Catches fire and melts	It melts. It gets gooey. Don't use it.		
PolyStyrene Foam	Catches fire	It catches fire, it melts, and only thin pieces cut. This is the #1 material that causes laser fires!!!		
PolyPropylene Foam	Catches fire	Like PolyStyrene, it melts, catches fire, and the melted drops continue to burn and turn into rock-hard drips and pebb		
Fiberglass	Emits fumes	It's a mix of two materials that cant' be cut. Glass (etch, no cut) and epoxy resin (fumes)		
Coated Carbon Fiber	Emits noxious fumes	A mix of two materials. Thin carbon fiber mat can be cut, with some fraying - but not when coated.		

Safe Materials

The laser can cut or etch. The materials that the laser can cut materials like wood, paper, cork, and some kinds of plastics. Etching can be done on almost anything, wood, cardboard, aluminum, stainless steel, plastic, marble, stone, tile, and glass.

Cutting

Material	Max thickness Notes		WARNINGS!	
Many woods	1/4"	Avoid oily/resinous woods	Be very careful about cutting oily woods, overy resinous woods as they also may cate fire.	
Plywood/Composite woods	1/4"	These contain glue, and may not laser cut as well as solid wood.		
MDF/Engineered woods	1/4"	These are okay to use but may experience a higher amount of charring when cut.		
Paper, card stock	thin	Cuts very well on the laser cutter, and also very quickly.		
Cardboard, carton	thicker	Cuts well but may catch fire.	Watch for fire.	
Cork	1/4"	Cuts nicely, but the quality of the cut depends on the thickness and quality of the cork. Engineered cork has a lot of glue in it, and may not cut as well.	Avoid thicker cork.	
Acrylic/Lucite/Plexiglas/PMMA	1/2"	Cuts extremely well leaving a beautifully polished edge.		
Thin Polycarbonate Sheeting (<1mm)	<1mm	Very thin polycarbonate can be cut, but tends to discolor badly. Extremely thin sheets (0.5mm and less) may cut with yellowed/discolored edges. Polycarbonate absorbs IR strongly, and is a poor material to use in the laser cutter.	Watch for smoking/burning	
Delrin (POM)	thin	Delrin comes in a number of shore strengths (hardness) and the harder Delrin tends to work better. Great for gears!		
Kapton tape (Polyimide)	1/16"	Works well, in thin sheets and strips like tape.		
Mylar	1/16"	Works well if it's thin. Thick mylar has a tendency to warp, bubble, and curl	Gold coated mylar will not work.	
Solid Styrene	1/16"	Smokes a lot when cut, but can be cut.	Keep it thin.	
Depron foam	1/4"	Used a lot for hobby, RC aircraft, architectural models, and toys. 1/4" cuts nicely, with a smooth edge.	Must be constantly monitored.	
Gator foam	2	Foam core gets burned and eaten away compared to the top and bottom hard paper shell.	Not a fantastic thing to cut, but it can be cut if watched.	
Cloth/felt/hemp/cotton		They all cut well. Our "advanced" laser training class teaches lace-making.	Not plastic coated or impregnated cloth!	
Leather/Suede	1/8"	Leather is very hard to cut, but can be if it's thinner than a belt (call it 1/8"). Our "Advanced" laser training class covers this.	Real leather only! Not 'pleather' or other imitations!	
Magnetic Sheet		Cuts beautifully	, , , , , , , , , , , , , , , , , , ,	
NON-CHLORINE-containing rubber		Fine for cutting.	Beware chlorine-containing rubber!	
Teflon (PTFE)	thin	Cuts OK in thin sheets		
Carbon fiber mats/weave hat has not had epoxy applied		Can be cut, very slowly.	You must not cut carbon fiber that has been coated!!	
Coroplast ('corrugated plastic')	1/4"	Difficult because of the vertical strips. Three passes at 80% power, 7% speed, and it will be slightly connected still at the bottom from the vertical strips.		

Etching

All the above "cut-able" materials can be etched, in some cases very deeply.

In addition, you can etch:

Material	Notes	WARNINGS!	
Glass	Green seems to work bestlooks sandblasted.	Only FLAT GLASS can be engraved in our cutter. No round or cylindrical items.	
Ceramic tile			
Anodized aluminum	Vaporizes the anodization away.		
Painted/coated metals	Vaporizes the paint away.		
Stone, Marble, Granite, Soapstone, Onyx. Gets a white "textured" look when etched.		100% power, 50% speed or less works well for etching.	

Section 12: Speed and Power Recommendations

60 Watt

	300 DPI RASTER ENGRAVING	400 DPI RASTER ENGRAVING	600 DPI RASTER ENGRAVING	VECTOR CUTTING
	SPEED/POWER	SPEED/POWER	SPEED/POWER	SPEED/POWER/FREQUENCY
Wood Cherry – Alder - Walnut	60/100	70/100	80/100	1/8" (3 mm) - 30/60/20 1/4" (6.4 mm) - 15/100/20 3/8" (9.5 mm) - 8/100/20 (two passes may produce better results)
Acrylic	100/50	100/40	100/30	1/8" (3 mm) - 12/100/100 1/4" (6 mm) - 4/100/100 3/8" (9.5 mm) - 2/100/100 (two passes may produce better results) Adjusting the standard focus distance so it is closer to the lens by about .030" will produce better edge quality on 1/4" and thicker acrylic.
AlumaMark	100/30	100/25	100/20	N/A
Anodized Aluminum	100/45	100/35	100/30	N/A
Painted Brass	100/30	100/25	100/20	N/A
Marbleized Painted Brass	100/40	100/35	100/30	N/A
Corian Or Avonite	25/100	35/100	45/100	½" (3 mm) - 50/80/100
Delrin Seals	100/40	100/30	100/20	60/85/100
Glass	40/100	50/100	60/100	N/A
Laserable Plastic	100/45	100/35	100/30	30/85/100
Leather	100/40	100/30	100/20	1/8" (3 mm) - 25/100/50
Marble	100/100	100/90	100/80	N/A
Mat board	100/65	100/55	100/45	50/40/50
Melamine	100/60	100/70	100/80	N/A
Stainless Steel With Cerdec Coating	N/A	80/100	70/100	N/A
Rubber & Rubber Stamps	20/100	30/100	40/100	25/100/100